

## Proposed Code Change State Form 41186R

RETURN TO: INDIANA DEPARTMENT OF HOMELAND SECURITY CODE SERVICES SECTION 302 W. Washington Street Room W246

Indianapolis, IN 46204

INSTRUCTIONS:

Only TYPED copy accepted.

(KEY – Dashed line through material to be deleted, underline material to be added)

FOR OFFICE USE ONLY

Received 1/18/10

Code 50.11.5.3-09

Code Title	Use second sheet for any material requiring more space.			
Section number and title R703.8 Flashing Proponent Cahvin Bolt Inspections and Testing Address S1310 Oriole Drive Warsaw, IN 46580 PROPOSED CODE CHANGE (Check One)    Change to read as follows   Add to read as follows   Delete and substitute as follows   Delete without substitution   R703.8 Flashing, Approved corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall carrivly or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall be installed at all of the following locations:   Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish. Approved corrosion-resistant flashing shall be installed at all of the following locations:   Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish to 1 to the water-resistive barrier for subsequent drainage.   At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.   Under and at the ends of masonry, wood or metal copings and sills.   Continuously above all projecting wood trim.   Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.   At wall and roof intersections.   REASON AND FISCAL IMPACT	Code Title		Edition	
Proponent Calvin Bolt Inspections and Testing Owner    Title	International Residential Code		2009	
Proponent Calvin Bolt Inspections and Testing Address 1310 Oriole Drive Warsaw, IN 46580 PROPOSED CODE CHANGE (Check One)  Change to read as follows Add to read as follows Delete and substitute as follows Delete without substitution  R703.8 Flashing. Approved corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shall extend to the surface of the exterior wall finish. Approved corrosion-resistant flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen balconies, surface attached, to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for Toloks," rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.	Section number and title		Page	
Address 1310 Oriole Drive Warsaw, IN 46580 PROPOSED CODE CHANGE (Check One) PROPOSED CODE CHANGE (Check One)    Change to read as follows   Add to read as follows   Delete and substitute as follows   Delete without substitution   R703.8 Flashing. Approved corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shall extend to the surface of the exterior wall finish. Approved corrosion-resistant flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.	R703.8 Flashing		370	
Address   1310 Oriole Drive Warsaw, IN 46580   574-269-3507	Proponent Title			
PROPOSED CODE CHANGE (Check One)    Change to read as follows   Add to read as follows   Delete and substitute as follows   Delete without substitution    R703.8 Flashing. Approved corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.    REASON AND FISCAL IMPACT	Calvin Bolt Inspections and Testing	Owner		
PROPOSED CODE CHANGE (Check One)  Change to read as follows Add to read as follows Delete and substitute as follows Delete without substitution  R703.8 Flashing. *Approved** corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shall extend to the surface of the exterior wall finish. *Approved** corrosion-resistant flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too, 1 have seen "balconies", "surface attached"; to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  REVIEW RECOMMENDATION  Approve	Address		Phone	
Change to read as follows Add to read as follows Delete and substitute as follows Delete without substitution  R703.8 Flashing. Approved corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shalls tend to the surface of the exterior wall finish. Approved corrosion-resistant flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed foor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION	1310 Oriole Drive Warsaw, IN 46580		574-269-3507	
R703.8 Flashing. Approved corrosion-resistant flashing shall be applied shingle-fashion in a manner to prevent entry of water into the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shall extend to the surface of the exterior wall finish. Approved corrosion-resistant flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  1 have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve	PROPOSED CODE CHANGE (Check One)			
the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shall extend to the surface of the exterior wall finish. Approved corrosion-resistant flashing shall be installed at all of the following locations:  1. Exterior window and door openings. Flashing at exterior window and door openings shall extend to the surface of the exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION	☐ Change to read as follows ☐ Add to read as follows ☐ De	elete and substitute as follows	Delete without substitution	
exterior wall finish or to the water-resistive barrier for subsequent drainage.  2. At the intersection of chimneys or other masonry construction with frame or stucco walls, with protection lips on both sides under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION	the wall cavity or penetration of water into the building structural framing components. Self-adhered membranes used as flashing shall comply with AAMA 711. The flashing shall extend to the surface of the exterior wall finish. Approved corrosion-resistant			
under stucco copings.  3. Under and at the ends of masonry, wood or metal copings and sills.  4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve				
4. Continuously above all projecting wood trim.  5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve				
5. Where exterior porches, decks, balconies, or stairs attach to a wall or floor assembly of wood-frame construction.  6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION	3. Under and at the ends of masonry, wood or metal copings and sills.			
6. At wall and roof intersections.  7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION	4. Continuously above all projecting wood trim.			
7. At built-in gutters.  REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve	5. Where exterior porches, decks, <u>balconies</u> , or stairs attach to a wall or floor assembly of wood-frame construction.			
REASON AND FISCAL IMPACT  I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve	6. At wall and roof intersections.			
I have seen balconies not flashed and caused severe mold and rot. This just clarifies the wording that they need to be flashed too, so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve	7. At built-in gutters.			
so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.  Large financial impact to the builder or homeowner would result later, if balconies are not flashed.  REVIEW RECOMMENDATION  Approve	REASON AND FISCAL IMPACT			
Approve	so that there is no loophole. (I can show the Judge in the code book during testimony that balconies have to be flashed too). I have seen "balconies", "surface attached", to the side of the house incorporating hidden steel (rather than using cantilevered floor joists), below a smaller window for "looks", rather than for human traffic.			
•	REVIEW RECOMMENDATION			
Disapprovo	Approve			
Disapprove				
Approve as amended				
Further Study				